# **Biosafety Risk Assessment: Safety Risk Groups**

### · Risk Group 1

- No or low individual and community risk
- Unlikely to cause human or animal disease

## Risk Group 2

- Moderate individual risk, low community risk
- Can cause disease but unlikely to be a serious hazard. Lab exposures may cause serious infection, but effective treatment and preventative measures are available and risk of spread of infection is limited

#### Risk Group 3

- High individual risk, low community risk
- Usually causes serious human or animal disease but does not ordinarily spread. Effective treatment and preventative measures are available.

#### Risk Group 4

- High individual and community risk
- Usually causes serious human or animal disease and can be readily transmitted. Effective treatment and preventative measures are not usually available